

CIL
EMU CRITICAL ITEMS LIST

Page: 1
Date: 12/02/91

12/24/91 SUPERSEDES 01/02/90

ANALYST:

NAME P/# DSY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
ELECTRICAL SIGNALS HARNESS, ITEM 152 SV789152-2 (1)	3/200	1520MHz: Electrical open or short, right or left microphone power lines.	END ITEM: Electrical open or short in right or left microphone lines.	A. Design: Each connector/cable interface is strain relieved by potting the conductors in place. A rubber backshell is then molded over the connector/cable interface. Each connector/adaptor ring interface is locked in place to prevent rotation by a mechanical lock and an adhesive lock. #24 AWG Teflon coated wire provides electrical/mechanical properties to prevent wire breaking. The conductors are bundled within a woven copper sheath over braided with a Nomex outer sheath. These cause the cables to act together and share any loading and resist any damage from abrasion and impact. Wire crimping per SVHS6909 (based on HSPC-Spec-D-1A).

CAUSES:
Cable chafing
against connector
shelt or shield.
Improper connector
strain relief.
Faulty connection
between the
connector and the
lead wires.

EMI INTERFACE:
Loss of one of two
microphone lines.

HIGH/MICROPHONE:
None for single
failure. Terminate
EVA with loss of
other line.

CREW/VEHICLE:
None.

B. Test -
Component Acceptance Test -
The 152 harness is subjected to acceptance testing prior to
final acceptance testing. This testing includes the
following tests which ensure there are no workmanship
problems which would cause an electrical short to ground or
an open circuit in the microphone signal HI/LO Lines.
The insulation resistance and dielectric strength between
each conductor and the shield ground is measured to ensure
there are no shorts.
Each connector/cable interface is pull tested (10 pounds) to
detect any workmanship problems which could cause a short
circuit.
Continuity testing of each conductor is performed after pull
testing to ensure there were no open circuits.

PDA Test -
The microphone signal HI/LO Lines are functionally checked
during PLSS PDA testing per DEMU-60-010, to ensure there are
no shorts to shield ground or opens which affect the
performance of the PLSS.

Certification Test -
This item has completed the structural, vibration and shock
certification requirements during 10/83. Engineering change
42M06-527-2 (added a connector pull test) has been
incorporated and certified since this configuration was
certified.

CML
EMU CRITICAL ITEMS LIST

Page: 2
Date: 12/02/91

12/24/91 SUPERSEDES 01/02/90

ANALYST:

NAME	FAILURE	MORE & CAUSES	FAILURE EFFECT	REASONABLE FOR ACCEPTANCE
P/N				
QTY	CRT			
3/28B	152TM1B;			<p>E. Inspection - To insure there are no workmanship problems which would cause a short or open circuit in the harness conductors, the following inspections are performed. Harness cables and conductors are visually inspected prior to assembly to insure there are no defects which would cause a short to ground or an open circuit due to defects in the cable insulation. Connector wiring is inspected before and after potting to insure there is no conductor damage and that the conductors are properly strain relieved and properly dressed to prevent shorting to the adapter ring or an open circuit. Insulation resistance and dielectric strength are measured between each conductor and shield ground to insure there are no shorts prior to and after potting of the connectors. Contact crimp samples are made prior to the start of contact crimping and at the conclusion of crimping and subjected to a pull test to insure the crimping tools are operating properly. This insures there will not be any high resistance problems at the connector.</p>

D. Failure History -

J-EMU-152-002 (4-11-85) During a pre-flight communications check, it was not possible to transmit through the right microphone on the ECA. The power failure was caused by a short circuit between the right microphone power line and the cable grounding shield. The insulation on the power line has been damaged prior to the cable assembly. EC 62808-527-2 was issued to create the SW789152-2 harness configuration by adding a connector pull test to the acceptance testing requirements.

Related Failures J-EMU-152-0003 (8-17-88) An open circuit in the hard-line comm. line was found during functional testing. The failure was determined to be caused by the pulling and twisting of the harness during normal installation on the PLSS.

This handling caused the wire to break. EC 62803-285 revised cable lengths and improved cable flexibility.

J-EMU-152-A001 (7-9-86) During PLSS Acceptance testing, all sensor outputs read full scale. A short circuit in the harness was found between Vref and ground. The short was due to improper assembly and testing by the vendor. The vendor's assembly and test

P-6
#80
1178
H1001

EMU - 1212

CIL
EMU CRITICAL ITEMS LIST

Page: 3
Date: 12/02/91

12/26/91 SUPERSEDES 01/02/90

ANALYST:

NAME	FAILURE	MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
3/200	1927H16:			procedures were revised.

E. Ground Turnaround -
Tested per EHQ-R-001, SEMU Communications and Slanted Check.

F. Operational Use -
Crew Response -
PROBLEMS/EVN: No response, single failure undetectable by crew or ground.
Training - Standard EMU training covers this failure mode.
Operational Considerations - Reference Loss/Failure Flight rules; define EMU as go with two-way RF communications. EVA checklist and EFP procedures verify hardware integrity and system operational status prior to EVA.